
Dress Code

Students should wear work clothes (jeans, pants, shorts, t-shirts, sweatshirts, tennis shoes, boots, any closed toe/heel shoe, etc.). No rings, watches, earrings, bracelets, necklaces, etc., or other metal objects should be worn during lab time. A student with hair that is shoulder length or longer needs to keep hair under a hat or in a ponytail tucked into his or her shirt.

Throughout the course of training at the Aviation Maintenance Technology Facility, students may be exposed to toxic chemicals and particulate matter. Such exposure is typical in the aviation industry. For this reason, all students must wear and use Personal Protection Equipment (PPE). Each student is personally responsible for proper wear and use of all PPE. A student who repeatedly does not wear or use PPE may be removed from class by the instructor and the student may fail the course. The student can return to class only at the instructor's discretion.

Eye Protection

Per Ohio Revised Code Section 3313.643, safety glasses **must** be worn when working in all lab and aircraft parking areas. Glasses must be clear and ANSI Z87.1-2015 certified. Students wearing prescription eyeglasses must wear side shields on their glasses.

Hearing Protection

Hearing protection must be worn at all times in the structural repair lab, hangar, and when working within 100 feet of an operating aircraft engine.

Earbuds/headphones for listening to music are not approved for hearing protection, and are forbidden from being worn in the laboratory, hangar, or aircraft parking areas.

Safety Shoes

Due to the nature of the work being performed, students are strongly urged to wear [Occupational Safety and Health Administration](#) (OSHA)-approved safety shoes. This footwear should be worn during all laboratory, hangar, and aircraft ramp activities.